

AnnexureD

BUILDINGSAFETYCERTIFICATE

No.CBSE/Admin/2026-2027/0018

Dated:24/06/2026

Certifiedthattheexistingbuilding **St.Anne'sSchool**(nameofthebuildingorpremises)at **P.No.A-4/1 to A-4/7, Sy.No.321, 325/5, 321/6 and 321/1/A, Electronic Complex, Kushalguda Vill, Kapra (m), Medchal-Malkajgiri (dist)** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+3	-	-	-	-	-

The building is owned/occupied by**St. Anne's School** (name of the Institution) have complied with the Building safety requirements inaccordancewith National Building codeRules, andverified by the officers concernedof**K. Vamshee Kishore** (NameofDepartment/Govt.)on **20/06/2026**(date of inspection)inthe presenceof**Sandhya Rani.Ch**(name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **04/05/2026** for a period of 10 years in accordance.
withruleandsubjectto complianceofthespecificconditionsas appended.

1. In future, if the building has any issues relating to any cracks, collapse and leakage of water it should be reported to concerned dept and immediate action should be taken.
2. Should Procure Fire Safety Certificate from Fire Dept their recommendations should be followed and updated regularly.
3. OriginalDocumentsoftheBuildingshouldbekept safety

*Strikeoutwhicheverisnot applicable.Incaseofblockismorethansixuseseparatesheetfor detail.

Signature with Seal:

Name:

Designation:

KVK CONSTRUCTION
Rep by **K. Vamshee Kishore**
Licence No- **BL / 3886 / 2019**
Valid up to : **14/10/2029**
Ph No : **9177090888**

Name& Address of Department/ Office:_____